



Service Information Letter

SIL 81439-XX-00-10

3700 IH 35 Waco, TX 76706 USA

PHONE: 1 (254) 662-0000

FAX: 1 (254) 662-9451

TO: All 2101 Approach Plus GPS OEM's, Operators, Service Centers and Installers

FROM: FreeFlight Systems Customer Support

SUBJECT: Release of new part numbers for the 2101 Approach Plus GPS Navigator.

PURPOSE: To notify Operators and Service Centers that new part numbers have been issued for the FreeFlight 2101 Approach Plus Navigator system.

Due to parts obsolescence, a replacement 12 channel GPS card was developed and incorporated into the 2101 Approach Plus Navigator. The FAA considers this upgrade a major change and has mandated new part numbers be assigned to reflect this alteration. There will be no change to the original form, fit or function of the unit. To the operator and installation technician this is a completely transparent change; both part numbers are interchangeable.

ACTION:

When ordering the 2101 Approach Plus, please reference the following chart:

- For P/N 81439-02-240X, use P/N 81439-32-240X
- For P/N 81439-03-240X, use P/N 81439-33-240X
- For P/N 81439-12-240X, use P/N 81439-42-240X

Customers with standing orders will have the PO modified and returned to them for approval.

The operating software for the 2101 Approach Plus system will be -240L (or later FAA approved software version).

ORIGINAL: September 4, 2008

SIL 81439-XX-00-10

PAGE 1 of 2



For Operators or Dealers who need additional information, please contact FreeFlight Systems Customer Support Department for assistance.

FreeFlight Systems
3700 Interstate 35 S.
Waco, TX 76706 USA

Attn.: Sales Dept.
Telephone: 1 (254) 662-0000
Fax: 1 (254) 662-9451

PUBLICATIONS AFFECTED:

SB 81439-XX-00-06, System s/w version 240B
SB 81439-XX-00-11, System s/w version 240D
82911, Component Maintenance Manual